

## PREVENTING UNSAFE OPERATION BY MONITORING SWITCHING MEANS AL MULDOON 269-983-2352

3/3









-.6V -.6V 3C

+5.6V

## FIGURE 3